







AUTOMATIC G.I.M.A.

TRANSFER MACHINES - ROTARY TABLES - MACHINING EQUIPMENTS
HORIZONTAL AND VERTICAL 3-AXIS CNC MACHINING CENTERS
MACHINING UNITS - SUPPORTS AND POSITIONING SLIDES

HORIZONTAL 3-AXIS CNC MACHINING CENTER WITH ELECTROSPINDLE



3AXCNC-O-E	
Feed	Ground ball screws $\varnothing 25p5$ mm
Guideways	Roller linear guideways size 25mm
X-axis useable stroke	150 mm
Y-axis useable stroke	95 mm
Z-axis useable stroke	145 mm
Forced lubrication	Linear guideways (12p), flanged nuts (3p)
Limit switches	24 Vdc inductive sensor / mechanical LS
Tool fitting	HSK-C50
Spindle motor	Asynchronous 3-phase 8,5kW
Spindle speed	100÷10000 RPM
Axis motor	Brushless 3,5Nm
Axis feed	1÷20000 mm/min
Tool internal cooling	Optional
Rigid tapping	Optional






AUTOMATIC GI.MA.

TRANSFER MACHINES - ROTARY TABLES - MACHINING EQUIPMENTS
HORIZONTAL AND VERTICAL 3-AXIS CNC MACHINING CENTERS
MACHINING UNITS - SUPPORTS AND POSITIONING SLIDES

HORIZONTAL 3-AXIS CNC MACHINING CENTER WITH ELECTROSPINDLE



3AXCNC-O-E

AUTOMATIC GI.MA. - Via F. Parri, 6 - Treviglio (BG) - Italy - Phone +39 0363 301004
E-mail info@automaticgima.it - Web site www.automaticgima.it