



AUTOMATIC GI.MA.

TRANSFER MACHINES - ROTARY TABLES - MACHINING EQUIPMENTS
HORIZONTAL AND VERTICAL 3-AXIS CNC MACHINING CENTERS
MACHINING UNITS - SUPPORTS AND POSITIONING SLIDES

PNEUMOHYDRAULIC ROTARY TABLE WITH HIRTH GEARS AND 6 SELF-CENTERING VISES



TRH-300-6-C	
<i>Vises clamping</i>	Pneumatic/hydraulic
<i>Rotary table clamping</i>	Pneumatic/hydraulic
<i>Rotation</i>	Pneumatic with hydraulic shock absorber
<i>Rotation direction</i>	Clockwise
<i>Hirth ring table</i>	Ø280 Z120
<i>Rotary table indexes</i>	6
<i>Indexing accuracy</i>	±8"
<i>Center accuracy</i>	±0.015
<i>Repeatability accuracy</i>	±0.015
<i>Table flatness</i>	±0.01
<i>Run-out of vise center hole</i>	±0.01

