




AUTOMATIC G.I.M.A.

TRANSFER MACHINES - ROTARY TABLES - MACHINING EQUIPMENTS
HORIZONTAL AND VERTICAL 3-AXIS CNC MACHINING CENTERS
MACHINING UNITS - SUPPORTS AND POSITIONING SLIDES

CNC ROTARY TABLE WITH HIRTH GEARS AND 8 SELF-CENTERING VISES



TRH-300-8-CN	
<i>Vises clamping</i>	Pneumatic/hydraulic
<i>Rotary table clamping</i>	Pneumatic/hydraulic
<i>Rotation</i>	Gear motor
<i>Rotation direction</i>	Clockwise
<i>Hirth ring table</i>	Ø280 Z120
<i>Rotary table indexes</i>	2/4/8
<i>Indexing accuracy</i>	±8"
<i>Center accuracy</i>	±0.015
<i>Repeatability accuracy</i>	±0.015
<i>Table flatness</i>	±0.01
<i>Run-out of vise center hole</i>	±0.01





AUTOMATIC G.I.M.A.

TRANSFER MACHINES - ROTARY TABLES - MACHINING EQUIPMENTS
HORIZONTAL AND VERTICAL 3-AXIS CNC MACHINING CENTERS
MACHINING UNITS - SUPPORTS AND POSITIONING SLIDES

TAVOLA ROTANTE A CN SU DENTATURA HIRTH A 8 MORSE AUTOCENTRANTI



TRH-300-8-CN

AUTOMATIC G.I.M.A. - Via F. Parri, 6 - Treviglio (BG) - Italy - Phone +39 0363 301004
E-mail info@automaticgima.it - Web site www.automaticgima.it